

IN REPLY REFER TO:

United States Department of the Interior

MINERALS MANAGEMENT SERVICE CENTRAL REGION

Oil Shale Office 131 North 6th Street, Suite 300 Grand Junction, Colorado 81501

August 16, 1982

Memorandum

To:

Files

From:

John Miley/Dave Oberwager

Subject: Tract U-a/U-b Inspection - Road Construction, Top Soil Stock Piles

Personnel Present

Dave Oberwager

OSO

John Miley

OSO

ACTIVITIES

Construction: Reviewed retention dam site, road construction, water haul road, storage warehouse site stripping operation, and ventilation shaft site locations.

Items of Concern:

- 1. Top soil pile along large road cut area is no longer in existence.
- 2. New area being stripped behind mine storage warehouse. All top soil material being wasted in draw, subject to water erosion loss.
- 3. Retention dam area should have more of alluvium saved and stored with the top soil stock pile.

Items Resolved

The top soil was used to cover the road fills for revegetation as planned.

Dave Oberwager

Environmental Specialist

John Milex

Mining Engineer

xc: J. Godlove - Ua/Ub

R. DeLeonarois - Ua/Ub

L. Ferguson - BLM, Vernal

D. Evans - BLM, Vernal

→ T. Portal - UDOGM

AUG 26 1982

DIVISION OF OIL, GAS & MINING